



JON M. HUNTSMAN, JR.  
Governor  
GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

**Inspection Report**  
**Minerals Regulatory Program**  
Report Date June 27, 2005

Supervisor 

**Mine Name:** Torrey Buff  
**Operator Name:** Jon Young

**Permit number:** S/055/012  
**Inspection Date:** May 11, 2005  
**Time:** about 3:25 to 3:50 PM

**Inspector(s):** Paul Baker and Doug Jensen  
**Other Participants:** None  
**Mine Status:** Active

**Weather:** Partly cloudy, cool

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:**

There was no specific purpose for the inspection. We were in the area and decided to check the site and to see if there were any signs of recent disturbance.

**Inspection Summary:**

12. Other

Comparing the photos we took with ones I took in January 2004, I cannot tell there has been any change. The site is shown in Photos 1 through 4. Although I did not measure the size of the area, I believe the disturbance to be less than one acre.

We found some tracks leading north, followed them, and found another smaller disturbance of which I had previously been unaware.

I used the GPS unit to take positions at the two sites, and a copy of the map I created with this data is attached to this report. Both of the sites are within a Trust Lands section (Section 16).

**Conclusions and Recommendations:**

I have no particular concerns at this time.


**Inspector's Signature** 

**Date:** June 27, 2005

PBB:jb

cc: Jon Young  
John Blake, SITLA  
Attachment: GPS & Photos





Dept. of Natural Resources  
Division of Oil, Gas & Mining  
Mineral Mines Program

Different data sources and input scales  
may cause misalignment of data layers.  
This product may not meet DOGM  
standards for accuracy and content.

200 0 200 400 Feet



Scale 1:10000  
Contour Interval: 40 feet



Mine Number: S/055/0  
Mine Name: Torrey Buff  
Township 29 S Range 5 E Section 16 SLBM  
Site is on the Torrey Quad, but the  
map includes part of the Twin Rocks Quad.

Drafted by PBB

May 11, 2005